

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: 26.05.2025

It is certified that the existing building ... DAV SCHOOL (name of the building or premises) at ... JOGIVITA, FULBARI (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3 STOREY	3 STOREY	NIL	NIL	NIL	NIL

The building is owned/occupied by ... DAV SCHOOL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of ER. SANJAY PRASAD GUPTA (Empanelled Engineer- SJDA) on 15.05.2025 (date of inspection) in the presence of TAPOSHI PAL BANIK, P.O-MAHANANDA BARRAGE, FULBARI, JALPAIGURI-734015 (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from...26.05.2025..... for a period of 20 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. NIL

Issued on 26.05.2025 at Siliguri by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : _____

Designation : _____

Name & Address of Department/ Office: _____

Er. Sanjay Prasad Gupta

Consulting Civil Engineer

SJDA-Empanelment Number A-87

Champasari, Siliguri

Cell : 98323-63651, 90021-51781

E-mail : snajay.gupta366@gmail.com