Annexure C

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No.	Dated: 19・06・20-25
It is certified that an inspection team headed	by Mr. Chandan Sharma, Asst. Engineer-II
(Name of Officers with designation) from	Siliguri Water Supply DivisionPHED
inspected the D.A.V School, Fulbari, Jogivit	a, Dist. Jalpaiguri-734015
(Name & Address of the school) on02,06,2	2025(date of inspection) and on the basis of
Water Test Report (Attached) bearing no	1766/SMSD/SD dated 12.06.2025
of DIST. LABORATORY AT FULBARI, SILIGURI	. (PHED Lab) certified that the
D.A.V School	(Name of school) has safe drinking water
facilities for the students and members of s	staff of the institution. School is also maintains the
hygienic sanitation condition in the school bui	ilding & the campus as per norms prescribed by the
Central/ State/ U.T. Govt.	Below
This certificate is valid till31,12,2026	10/06/25
	Signature with Seal: Pradham Panchayat
To	Name : RAFIRajeani, Jaloaguri Designation : PRADHAN Name & Address of the Office / Department :
Principal D.A.V School, Fulbari, Dist. Jalpaiguri- 734015 (Name & Address of the Institution)	Fulbari 2G.P, Fulbari Hart Jalpaiguri, WB.